

TAIN AIRFIELD**Building Record****Area K****No. 4****NGR NH****Description**

To the W of the entrance to Loans of Bogbain Farm are the remains of 3 structures thought to belong to the war time use of Tain Airfield. The remains include a red brick store with glass set in concrete on the wall head. An iron framed gate with wire mesh still survives here. To the W is a grey brick foundation also topped with glass embedded mortar at it wall head. It is partially banked with soil. Between these 2 standing structures is a T-shaped foundation. Other foundations may lie in the woodland to the W and E, though this area was not surveyed further

Condition

The standing structures are in good condition.

Interpretation

There may have been another camp site at this position, now largely removed. Alternatively the remains may mark part of a guard post on one of the routes of entry to the airfield.

Importance

Low

**Photograph No.****33B****Date 02/07/99****Looking****NE at all 3 structures**